



Crest Building Consultancy Ltd
5382 Parker Avenue
Victoria
V8Y 2M9
Tel: (250) 888 9182
Fax: (250) 727 3723
Email: leeottewell@shaw.ca
Web: www.crestbc.ca

BUILDING INSPECTION



Address of Property: 31 Olive Street, Oak Bay

Date of Inspection: July 17th 2006

Client: Ivan House

Inspector: Lee Ottewell (BPCPA License #: 47384)

Report Index

THE REPORT

| | |
|---|----|
| INSPECTION CONDITIONS | 1 |
| SITE | 2 |
| EXTERIOR OF BUILDING | 3 |
| ROOF | 6 |
| GARAGE/CARPORT | 7 |
| ELECTRICAL | 8 |
| ATTIC & VENTILATION | 9 |
| STRUCTURAL | 10 |
| HEATING, VENTILATION & AIR CONDITIONING | 12 |
| PLUMBING SYSTEM | 14 |
| INTERIOR | 16 |

THE REPORT

INSPECTION CONDITIONS

Client Information:

Inspection Date: July 17th 2006.

Client's Name: Ivan House.

Address of Property Inspected: 31 Olive Street, Oak Bay.

MLS Number: 342323.

Access Provided By: Via the buyer's agent.

Weather Conditions:

Inspection Day Weather: Clear.

Temperature At The Time Of The Inspection: Between 5 & 10 degrees celsius.

Soil Conditions: Damp.

Building Characteristics:

Approximate Year In Which The Building Was Built: 2005.

Building Type: Single Family House.

Other Information:

Building Occupied During Inspection? No.

Client Present During Inspection?: No.

SITE

Site:

Orientation: For the purposes of this report all directional references to left, right, front, or rear assume the reader is standing at the street facing the building being inspected.

Surface Drainage: Satisfactory - The lot appears to have adequate drainage to prevent water from accumulating against the house.

Drainage In Front Of The Garage/ Carport: Due to driveway sloping away from the house there isn't a requirement to have drainage in front of the garage.

Driveway:

Driveway Material: Concrete.

Driveway Condition: Satisfactory - The driveway surface is in satisfactory condition with only normal deterioration noted.

Walkway:

Walkway Materials: Concrete.

Walkway Condition: Satisfactory - The walkways surface material is in satisfactory condition with only normal deterioration noted.

Patio

Patio Condition: Satisfactory - The patio surface material is in satisfactory condition with only normal deterioration noted.

Patio Floor Materials: Concrete.

Utility Services:

Electric Service: Underground.

Service Meter Entrance: Satisfactory - The meter housing appears to be correctly installed.

Gas Service: The house is connected to a mains gas supply.

Gas Odour Noted: No.

EXTERIOR OF BUILDING

Exterior:

Exterior Siding Materials:

Combination of: Fibre Composite Panels (also known as 'Hardy Plank') and Cedar Shingles.

Siding:

Satisfactory - The siding is in serviceable condition.

Trim:

Satisfactory - The trim is intact and satisfactory.

Soffit:

Satisfactory - The soffits are in a satisfactory condition.

Fascia & Barge Boards:

Satisfactory - The fascia and barge boards appear to be in satisfactory condition and show only signs of normal wear.

Windows:

Satisfactory - The window framing and trim are in a satisfactory condition.

Door & Window Flashings:

Satisfactory - The installed flashings appear to be adequate.

Painted Surfaces:

Satisfactory - The finish or exposed painted surfaces are satisfactory.

Front Outside Entry Door:

Satisfactory - The outside entry door is satisfactory as noted from the exterior.

Left Outside Entry Door:

Satisfactory - The outside entry door is satisfactory as noted from the exterior.

Rear Outside Entry Door:

Satisfactory - Both the rear outside entry doors are satisfactory as noted from the exterior.

Windows Type:

A mixture of Sliders & Fixed.

Glazing:

Double.

Downspouts:

The downspouts appear to be clear and functional.

Ground Fault Circuit Interrupters (GFCI):

All external outlets are correctly GFCI protected.

Siding Too Close to Grade:

Satisfactory - There appears to be adequate clearance between the soil and siding.

Comments:



Action Necessary - It is good practice to have a gap where siding or trim meet horizontal flashings to prevent water from 'wicking up'. The gaps around the flashings on this house were poor (and in some instances none existing).

Foundation:

Type of Foundation:

Crawlspace.

Foundation Materials:

Poured in place concrete.

Visible Portions of Exterior Foundation:

The exterior view of the foundation is limited to the portions visible above grade. Only about 5% to 10% of the foundation was visible.

Visible Foundation Cracks Noted From Exterior:

No significant cracking in the foundation walls was noted during the exterior examination.

Evidence of Recent Movement:

No - There is no evidence of any recent movement.

Perimeter Foundation Drains:

Sections of Perimeter Drain Tile Visible:

Yes - At least one end of the drain exposed to daylight was noted. This inspection does not warrant the effectiveness of the drainage system. I merely noted that there appears to be one present.

Type of Drainage Tile:

Plastic.

Deck, Entrance, Porch or Balcony :

Location:

There is a:

Supporting Columns:

Railings:

Flooring Material:



Action Necessary - The edges of the concrete porch floor are inadequately supported. This will eventually cause the concrete to crack.

ROOF

Roof:

Means of Roof Inspection:

The roof covering was inspected by walking on the roof.

Type Roof:

Sloped.

Roof Covering Materials:

Asphalt shingles. These consist of cellulose or fiberglass matting which is impregnated with asphalt and then has a coloured gravel applied on the surface to prevent ultraviolet deterioration. It is then cut into individual shingles.

Cover Layers:

The roof covering on the main structure appears to have one layer.

Condition of Main Roof Covering Material:

Good - The roof covering material is either new or near new, and it appears to be installed correctly.

Ridges/Hips:

Satisfactory - The ridge/hip covering material appears to be in satisfactory condition.

Flashings:

Satisfactory - The flashings around openings in the roof covering appear to be watertight and caulked as needed.


Valleys:

Satisfactory - The valleys appear to be in satisfactory condition.

Evidence of Leakage:

No.

Gutters:



Attention Needed - The gutters need cleaning out. It is also prudent to re-caulk all the joints periodically.

GARAGE/CARPORT

Garage/Carport:

| | |
|--|---|
| Garage Type: | The garage is attached. |
| Number of Vehicle Doors: | There is a single overhead door. |
| Vehicle Door Condition: | Satisfactory - The vehicle door(s) is(are) in satisfactory condition, and functional. |
| Vehicle Door Opener(s): | The overhead door opener appears to function appropriately. |
| Safety Reverse Mechanism on Garage Door(s): | Yes - Safety reverse mechanisms are in place and are functioning correctly. |
| Floor Condition: | Satisfactory - The garage floor is in satisfactory condition. |
| Garage Walls Condition: | Satisfactory - The wall covering and framing appears to be in satisfactory condition. |
| Ceiling: | Satisfactory - the ceiling covering appears to be in a satisfactory condition. |
| Windows: | None - There are no windows in this room. |
| Fire Rated Entry Door to Structure: | Yes - There is a fire rated door separating the garage from the living areas of the house. |
| Electric Outlets in Garage: | Satisfactory - The electrical outlets in the garage tested as correctly wired and grounded. |

ELECTRICAL

Main Power Panel:

| | |
|--|--|
| Service Size: | 200 amps. |
| Service Cable to Panel Type: | Aluminum. |
| Is Panel Accessible: | Yes - The electrical panel is in a location that makes it readily accessible. |
| Panel Type: | Breaker type power panel. |
| Panel Cover Removed: | Yes. |
| Panel Condition: | Satisfactory - The power panel, as a container for safely covering electrical circuitry and components, is functioning as intended, minimizing the risk of electrical shock. |
| Breaker/Fuse to Wire Compatibility: | Satisfactory - The breakers/fuses in the main power panel appear to be appropriately matched to the circuit wire gauge. |
| Legend Available: | Yes - Identification of the breakers and the appliances or areas they control are clearly marked. This inspection does not verify the accuracy of this legend. |
| Condition of Wiring in Panel: | Satisfactory - Electrical circuitry wiring in the panel appears neatly arranged with no unallowable splices. |
| Circuit Wiring Type: | Copper - The structure is wired using plastic insulated copper single conductor cables. |
| Main Service Ground Verified: | No - The main service ground wire was not verified by the inspector. What this means is that the he was not able to see the grounding wire along it's entire length from the panel to the grounding source (copper pipe, rods etc). This is common if the wire is hidden behind walls etc. |

Miscellaneous:

| | |
|----------------------------------|--|
| Smoke Detectors: | Yes - The building is equipped with smoke or heat detectors. The detectors were not tested, they were merely noted as being present. It is important for you to test them on a regular basis, monthly at least. |
| Doorbell : | Yes - At least one exterior door has a working doorbell. |
| Central Vacuum Installed: | No. |

ATTIC & VENTILATION

Attic & Ventilation:

| | |
|--|--|
| Method of Inspection: | The both attic spaces were entered. |
| Roof Framing Type: | A truss system is installed in the attic cavity that is used to support the roof and transmit the roof load to the exterior walls. |
| Roof Framing Condition: | Satisfactory - The roof framing appears to be in functional condition. |
| Evidence of Leaks on Interior of Attic: | There is no evidence of current water leaks into the accessible attic spaces. |
| Roof Ventilation: | Roof Vents & Soffit Vents. |
| Baffles: | There are baffles between the insulation and the roof sheathing at the eaves to allow the air to circulate from the soffit vents. |
| Vapour Barrier Installed: | A section of insulation was lifted and a vapour barrier was seen. |
| Insulation Noted: | The following type of insulation was noted in the attic: Cellulose. Blown in place. |
| Insulation Conditions: | Satisfactory - The attic insulation appears to be adequate and properly installed. The garage has a lower amount of insulation above it's ceiling. |
| Heat Recovery Ventilator: | None installed. |
| Bathroom/Kitchen/Dryer Vents: | Satisfactory - the visible vents from the bathroom(s) and kitchen range hood(s) appear to correctly discharge externally. |
| Comments: | Note some areas of the attic space were inaccessible and therefore not inspected. |

STRUCTURAL

GENERAL:

Type of Construction:

Wood Frame.

Building Overview:

There were no obvious visible signs of structural problems with this property. The walls, floors, ceilings did not show any signs of stress, cracking, displacement, bowing or buckling.

CRAWLSPACE

Crawlspace Inspected By:

The crawlspace was inspected by entering and crawling through.

Crawlspace Ceiling Exposed Percent:

Most of the ceiling is open allowing visibility of the ceiling/floor joists.

Pony Walls:

The floor joists are supported on Pony Walls rather than a main beam - these are basically internal structural framing transferring the load of the floor onto a concrete foundation.

Condition of Pony Wall(s):

Satisfactory - The pony wall(s) supports are in satisfactory condition.

Floor Joists Condition:



Attention Necessary - some of the larger joists spans didn't have any cross bracing.

Percent Interior Foundation Wall Exposed:

The interior view of the foundation is limited to the visible portions of the walls. Foam Board insulation obscured the majority of the inside of the foundation wall.

**Conditions Noted
in Foundation
Walls, Interior
View:**

Satisfactory - The exposed visible portions of the interior foundation perimeter walls appear to be satisfactory.

Insulation Noted:

Yes the following type is used: Fibreglass & Foam Board.

**Insulation
Conditions:**

Satisfactory - The insulation appears to be adequate and properly installed.

**Evidence of
Recent Movement
In Foundation
Wall:**

No - There is no evidence of any recent movement in the visible sections of foundation wall.

**Foundation Bolts
Noted:**

Yes - This inspection noted the presence of foundation bolts correctly used to secure the framing to the foundation.

**Moisture on
Exposed
Crawlspace Walls
Noted:**

No - There was no visual evidence of elevated moisture levels noted on the exposed areas of the crawlspace walls.

Crawlspace Floor:

Concrete.

HEATING, VENTILATION & AIR CONDITIONING

Electric Baseboards:

Electric Baseboard Heaters:

Satisfactory - The electric baseboard heaters were sampled and of all those tested they worked satisfactory.

Fire Precautions - Electric Baseboard Heaters:

Electric baseboard heaters - clearances to draperies

To reduce the risk of fires always ensure that there is a minimum clearance of 8 inches above baseboard heaters and 3 inches in front eg proximity of curtains, beds etc. Also keep electrical cables away from the heaters because they can melt.

Electric Convector Heaters:

Electric Convector Heaters:

Satisfactory - The electric heaters were sampled and of all those tested they worked satisfactory.

Fireplace:

Location of Fireplace:

Living Room.

Type of Fireplace:

There is a gas fire installed.

Gas Service.

Recommend having the gas fire serviced. This should be done annually along with any other gas appliances in the building.

**Carbon Monoxide
Tested.**

No carbon monoxide was detected around the gas fire.

PLUMBING SYSTEM

Plumbing:

Public Service Piping Material:

The main service line to the structure is plastic.

Main Water Line Shutoff Location:

Garage.

Visible Mineral Deposits or Encrustations:

No.

Interior Supply Piping Material:

Predominantly Plastic with some copper.

Supply Piping Condition:

No.

Water Pressure:

Satisfactory - The shower pressure was still functional when several other fixtures were using water.

Waste & Vent Pipe Materials

Plastic.

Waste & Vent Piping Condition:

Satisfactory - The visible plumbing waste piping appears functional.

Objectionable Odours Noted:

No.

Water Heater :

Location:

In the garage.

Age:

This tank is new. The average lifespan of a water heater is about 10 years.

Tank Capacity:

A 50 gallon water heater is installed and is recommended for a large family or a home with a spa tub.

Fuel Source for Water Heater:

The water heater is gas-fired.

Exposed Water Heater Condition:

Satisfactory - It shows some age, but it appears sound.

Drip Leg Installed for Natural Gas-Fired Unit:

Yes - There is a drip leg installed on the incoming gas line to the water heater. This reduces the risk of debris clogging the gas valve.

Gas Shut Off:

Satisfactory - There is a gas shut off installed adjacent to the hot water tank.

Flue/Exhaust Pipe

Condition:

Satisfactory - The exhaust flue appears to be correctly installed.

Water Piping

Condition:

Satisfactory - The incoming and output piping is installed correctly.

Cold Water Supply

Shut Off Valve:

Yes - There is a shut off valve installed on the incoming water line. This valve can be used to cut off the water supply to the water heater.

Temperature &

Pressure Relief

Valve:

Satisfactory - The temperature and pressure relief valve is of the correct rating for the water heater.

Discharge Tube:

Satisfactory - The discharge tube is correctly installed.

Water Heater

Insulation Jacket:

Integral.

Strapping:

There is metal strapping around the tank to reduce the risk of pipe ruptures in the event of earthquakes.

INTERIOR

Staircase:

Staircase Condition:

Satisfactory - The main staircase is appropriately installed. There is a handrail installed. The staircase is adequately lighted.

Electrical Outlets:

Satisfactory - The outlets tested in this room are correctly wired and grounded.

Light and Light Switch.

Satisfactory - The light(s) and switch(es) were functional at the time of the inspection.

Heat Source Noted:

There is a heat source in this room.

Upper Level Hallway:

Walls:

Satisfactory - The walls in this room appear to be satisfactory.

Ceiling:

Satisfactory - The ceiling is functional and as expected.

Floor:

Satisfactory - The floor in this room is in satisfactory condition.

Windows:

Satisfactory - The window(s) and associated hardware in this room are all satisfactory.

Electrical Outlets:

Satisfactory - The outlets tested in this room are correctly wired and grounded.

Light and Light Switch.

Satisfactory - The light(s) and switch(es) were functional at the time of the inspection.

Living Room:

Outside Entry Door:

The outside entry door is satisfactory.

Walls:

Satisfactory - The walls in this room appear to be satisfactory.

Ceiling:

Satisfactory - The ceiling is functional and as expected.

Floor:

Satisfactory - The floor in this room is in satisfactory condition.

Windows:

Satisfactory - The window(s) and associated hardware in this room are all satisfactory.

Electrical Outlets:

Satisfactory - The outlets tested in this room are correctly wired and grounded.

Light and Light Switch.

Satisfactory - The light(s) and switch(es) were functional at the time of the inspection.

**Heat Source
Noted:**

There is a heat source in this room.

Kitchen:

Walls:

Satisfactory - The walls in this room appear to be satisfactory.

Ceiling:

Satisfactory - The ceiling is functional and as expected.

Floor:

Satisfactory - The floor in this room is in satisfactory condition.

Windows:

None - There are no windows in this room.

Electrical Outlets:



**Light and Light
Switch.**

Action Necessary - There was a non functioning light in this room. I did not determine if this was a fault or if the bulb is blown and needs replacing.

**Heat Source
Noted:**

There is a heat source in this room.

Countertops:

Satisfactory - The countertops in the kitchen are satisfactory.

**Cabinets, Drawers,
and Doors:**

Satisfactory - The cabinets, doors, and drawers are satisfactory in both appearance and function.

**Faucet and Supply
Lines:**

Satisfactory - Faucets and supply lines appear satisfactory with no leaks noted.

**Sink and Drain
Lines:**

Satisfactory - The sink and drainage lines appear to be satisfactory.

**Food Waste
Disposal:**

Satisfactory - The food waste disposal appears to be functional. No food was ground up in this inspection. The inspector was unable to determine if the unit will grind food waste adequately.

Range Hood:

Satisfactory - The range hood and exhaust fan appeared to work correctly on one or both speeds. There is a filter installed, and it will require periodic cleaning.

Dining Room:

Walls:

Satisfactory - The walls in this room appear to be satisfactory.

Ceiling:

Satisfactory - The ceiling is functional and as expected.

Floor:

Satisfactory - The floor in this room is in satisfactory condition.

Windows:

Satisfactory - The window(s) and associated hardware in this room are all satisfactory.

Electrical Outlets:

Satisfactory - The outlets tested in this room are correctly wired and grounded.

Light and Light Switch.

Satisfactory - The light(s) and switch(es) were functional at the time of the inspection.

Heat Source Noted:

There is a heat source in this room.

Family Room:

Entry Door:

Satisfactory - The entry door to this room is functional.

Walls:

Satisfactory - The walls in this room appear to be satisfactory.

Ceiling:

Satisfactory - The ceiling is functional and as expected.

Floor:

Satisfactory - The floor in this room is in satisfactory condition.

Windows:

Satisfactory - The window(s) and associated hardware in this room are all satisfactory.

Electrical Outlets:

Satisfactory - The outlets tested in this room are correctly wired and grounded.

Light and Light Switch.

Satisfactory - The light(s) and switch(es) were functional at the time of the inspection.

Heat Source Noted:

There is a heat source in this room.

Template Laundry:

Linen Closet:

Satisfactory - The closet is functional and of average size.

Walls:

Satisfactory - The walls in this room appear to be satisfactory.

Ceiling:

Satisfactory - The ceiling is functional and as expected.


| | |
|--------------------------------|---|
| Floor: | Satisfactory - The floor in this room is in satisfactory condition. |
| Windows: | None - There are no windows in this room. |
| Electrical Outlets: | Satisfactory - The outlets tested in this room are correctly wired and grounded. |
| Light and Light Switch. | Satisfactory - The light(s) and switch(es) were functional at the time of the inspection. |
| Heat Source Noted: | There is a heat source in this room. |
| Dryer Ventilation: | Satisfactory - The dryer ventilation as installed appears adequate. |
| Laundry Basin: | Yes - There is a laundry basin installed. The unit is functional. No leaks were noted. |

Master Bedroom:

| | |
|--------------------------------|---|
| Outside Entry Door: | The outside entry door is satisfactory. |
| Entry Door: | Satisfactory - The entry door on the master bedroom is as I expected, and it is functional. |
| Walls: | Satisfactory - The walls in this room appear to be satisfactory. |
| Ceiling: | Satisfactory - The ceiling is functional and as expected. |
| Floor: | Satisfactory - The floor in this room is in satisfactory condition. |
| Windows: | Satisfactory - The window(s) and associated hardware in this room are all satisfactory. |
| Electrical Outlets: | Satisfactory - The outlets tested in this room are correctly wired and grounded. |
| Light and Light Switch. | Satisfactory - The light(s) and switch(es) were functional at the time of the inspection. |
| Heat Source Noted: | There is a heat source in this room. |
| Entry Door: | Satisfactory - The entry door to the laundry room is functional. |

Template Bedroom:

Closet(s):



Ensuite Bathroom:

| | |
|---------------------------------|---|
| Location: | Off the master bedroom. |
| Entry Door: | Satisfactory - The entry door to the bathroom is as I expected, and it is functional. |
| Walls: | Satisfactory - The walls in this room appear to be satisfactory. |
| Ceiling: | Satisfactory - The ceiling is functional and as expected. |
| Floor: | Satisfactory - The floor in this room is in satisfactory condition. |
| Ventilation Fans: | Satisfactory - There is an exhaust fan installed in this bathroom, and it is performing satisfactorily. |
| Windows: | Satisfactory - The window(s) and associated hardware in this room are all satisfactory. |
| Electrical Outlets: | Satisfactory - The outlet in the bathroom is correctly GFCI protected. |
| Light and Light Switch. | Satisfactory - The light(s) and switch(es) were functional at the time of the inspection. |
| Heat Source Noted: | There is a heat source in this room. |
| Vanity Cabinet: | Satisfactory - The vanity cabinet and top in this bathroom are satisfactory. |
| Basin and Drain Fixture: | Satisfactory - The basins and drainage fixtures appear to be satisfactory. |

Faucet and Supply

Lines: Satisfactory - Faucets and supply lines appear satisfactory.

Toilet Condition: Satisfactory - The toilet appears to be functional.

Tub: Satisfactory - the bath tub is not damaged and functions as intended.

Tub Faucets: Satisfactory - The tub faucets operate as intended.

Tub Walls: Satisfactory - The walls appear to be in satisfactory condition.

Tub Drain: Satisfactory - The tub appears to drain at an acceptable rate.

Shower Pan: Satisfactory - the shower pan is not damaged and functions as intended.

Shower Faucets: Satisfactory - The shower faucets operate as intended.

Shower Walls: Satisfactory - The walls appear to be in satisfactory condition.

Shower Drain: Satisfactory - The shower appears to drain at an acceptable rate.

Glass Tub/Shower Door: None.

Caulking Satisfactory - The caulking in the water contact areas appears to be satisfactory.

Bedroom 2 :

Entry Door: Satisfactory - The entry door to this bedroom is as I expected, and it is functional.

Walls: Satisfactory - The walls in this room appear to be satisfactory.

Ceiling: Satisfactory - The ceiling is functional and as expected.

Floor: Satisfactory - The floor in this room is in satisfactory condition.

Windows: Satisfactory - The window(s) and associated hardware in this room are all satisfactory.

Electrical Outlets: Satisfactory - The outlets tested in this room are correctly wired and grounded.

Light and Light Switch. Satisfactory - The light(s) and switch(es) were functional at the time of the inspection.

Heat Source Noted: There is a heat source in this room.

Closet: Satisfactory - The closet is in a satisfactory condition.

Bedroom 3 :

| | |
|--------------------------------|---|
| Entry Door: | Satisfactory - The entry door to this bedroom is as I expected, and it is functional. |
| Walls: | Satisfactory - The walls in this room appear to be satisfactory. |
| Ceiling: | Satisfactory - The ceiling is functional and as expected. |
| Floor: | Satisfactory - The floor in this room is in satisfactory condition. |
| Windows: | Satisfactory - The window(s) and associated hardware in this room are all satisfactory. |
| Electrical Outlets: | Satisfactory - The outlets tested in this room are correctly wired and grounded. |
| Light and Light Switch: | Satisfactory - The light(s) and switch(es) were functional at the time of the inspection. |
| Heat Source Noted: | There is a heat source in this room. |
| Closet: | Satisfactory - The closet is in a satisfactory condition. |

Bathroom:

| | |
|---------------------------------|---|
| Location: | Upper Hallway. |
| Entry Door: | Satisfactory - The entry door to the bathroom is as I expected, and it is functional. |
| Walls: | Satisfactory - The walls in this room appear to be satisfactory. |
| Ceiling: | Satisfactory - The ceiling is functional and as expected. |
| Floor: | Satisfactory - The floor in this room is in satisfactory condition. |
| Ventilation Fans: | Satisfactory - There is an exhaust fan installed in this bathroom, and it is performing satisfactorily. |
| Windows: | Satisfactory - The window(s) and associated hardware in this room are all satisfactory. |
| Electrical Outlets: | Satisfactory - The outlet in the bathroom is correctly GFCI protected. |
| Heat Source Noted: | There is a heat source in this room. |
| Vanity Cabinet: | Satisfactory - The vanity cabinet and top in this bathroom are satisfactory. |
| Basin and Drain Fixture: | Satisfactory - The basin and drainage fixture appears to be satisfactory. |
| Faucet and Supply Lines: | Satisfactory - Faucets and supply lines appear satisfactory. |

| | |
|--------------------------------------|--|
| Toilet Condition: | Satisfactory - The toilet appears to be functional. |
| Tub: | Satisfactory - the bath tub is not damaged and functions as intended. |
| Tub Faucets: | Satisfactory - The tub faucets operate as intended. |
| Tub & Shower Walls: | Satisfactory - The walls appear to be in satisfactory condition. |
| Tub Drain: | Satisfactory - The tub appears to drain at an acceptable rate. |
| Glass Tub/Shower Door: | None. |
| Caulking/Water Contact Areas: | Satisfactory - The caulking in the water contact areas appears to be satisfactory. |

Washroom:

| | |
|--------------------------------------|---|
| Location: | Main Hallway. |
| Entry Door: | Satisfactory - The entry door to the bathroom is as expected, and it is functional. |
| Walls: | Satisfactory - The walls in this room appear to be satisfactory. |
| Ceiling: | Satisfactory - The ceiling is functional and as expected. |
| Floor: | Satisfactory - The floor in this room is in satisfactory condition. |
| Ventilation Fans: | Satisfactory - There is an exhaust fan installed in this bathroom, and it is performing satisfactorily. |
| Windows: | None - There are no windows in this room. |
| Electrical Outlets: | Satisfactory - The outlet in the bathroom is correctly GFCI protected. |
| Light and Light Switch: | Satisfactory - The light(s) and switch(es) were functional at the time of the inspection. |
| Heat Source Noted: | No. |
| Basin and Drain Fixture: | Satisfactory - The basin and drainage fixture appears to be satisfactory. |
| Faucet and Supply Lines: | Satisfactory - Faucets and supply lines appear satisfactory. |
| Toilet Condition | Action Necessary - The toilet in this bathroom is blocked. |
| Caulking/Water Contact Areas: | Satisfactory - The caulking in the water contact areas appears to be satisfactory. |