

**CODE 51
CODE 53
CODE 55**
5.7L "Y" SERIES
FUEL INJECTION (PORT)

**CODE 51
FAULTY MEM-CAL**

CHECK THAT ALL PINS ARE FULLY INSERTED IN THE SOCKET. IF OK, REPLACE ,
MEM/CAL, CLEAR MEMORY, AND RECHECK. IF CODE 51 REAPPEARS, REPLACE ECM.

**CODE 53
SYSTEM OVER VOLTAGE**

- THIS CODE INDICATES THERE IS A BASIC GENERATOR PROBLEM .
- CODE 53 WILL SET IF VOLTAGE AT ECM TERMINAL B2 IS GREATER THAN 17.1 VOLTS FOR 2 SECONDS .
 - CHECK AND REPAIR CHARGING SYSTEM. SEE SECTION 6D .

CODE 55

BE SURE ECM GROUNDS ARE OK. IF OK
REPLACE ELECTRONIC CONTROL MODULE (ECM)

CLEAR CODES AND CONFIRM "CLOSED LOOP" OPERATION AND NO "SERVICE ENGINE SOON" LIGHT.

4-4-85
*6S 2652-6E